Oil Field Environmental Incident Summary

Responsible Party: CONTINENTAL RESOURCES, INC. **Well Operator:** CONTINENTAL RESOURCES, INC.

Well Name: OVERLOON 1-34H1

Field Name: UKRAINA Well File #: 26956

Date Incident: 4/30/2014 Time Incident: 12:00 Facility ID Number:

County: BILLINGS Twp: 141 Rng: 98 Sec: 34 Qtr: SW

Location Description: stubble field and county round r/w

Submitted By: Todd Senescall Received By:

Contact Person: Todd Senescall

PO BOX 268870

OKLAHOMA CITY, OK 73126

General Land Use: Cultivated Affected Medium: Topsoil

Distance Nearest Occupied Building:

Distance Nearest Water Well:

Type of Incident: Other

Release Contained in Dike: No Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil

Brine

Other 1 Barrels 0.5 Barrels 1 barrels

Description of Other Released Contaminant:

drilling fluid

Inspected: Written Report Received: 12/21/2016 Clean Up Concluded: 5/20/2014

Risk Evaluation:

none

Areal Extent:

An 80' X 300' area of county road r/w and stubble field was misted.

Potential Environmental Impacts:

soil, vegetation

Action Taken or Planned:

Recoverable fluid on location was recovered. The rest will be recovered when equipment is moved. Misted vegetation of of location will be mowed and recovered pending landowner permission. Soil analyses will be conducted to determine if additional remediation is warranted. Nichole Anderson was notified via voicemail.

Driller needs to insure that both mud pumps are off and the top drive is depressurized before rotating out of the stand.

Wastes Disposal Location: TBD

Agencies Involved: Billings County road superintendent

Updates

Date: 5/1/2014 Status: Reviewed - Follow-up Required Author: Roberts, Kris

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Release sprayed off location. Follow-up is necessary.

Date: 5/5/2014 Status: Inspection Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

The weather was 63 °F, clear, with wind from the southeast 10-15 mph. The site is actively being drilled for new wells. Drilling mud from the rig misted on the ditch, road, and stubble field on the south side of well pad. The vegetation in the ditch that was impacted has been mowed and hauled away. There is still a little staining on top edge of ditches. The stubble field has not been touched and has not been seeded. Follow-up required to check on vegetative growth.

Date: 7/7/2014 Status: Inspection Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

The weather was 67 °F, cloudy, with wind from the northwest 15 to 20 miles per hour. The vegetation in the ditches is growing and looks good. The cropland was never seeded to the south or around the well. There was a piece of equipment parked in the south field; it appears that a pipeline is being placed in the ground. No further follow-up needed at this time.

Date: 11/19/2014 Status: Correspondence Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Sample results of cleanup.

Date: 11/24/2014 Status: Correspondence Author: Espe, Brady

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Received sample results.

Date: 3/9/2016 Status: Correspondence Author: Suess, Bill

Updated Oil Volume:

Updated Salt Water Volume:

Updated Other Volume:

Updated Other Contaminant

Notes:

Bill Suess sent a No Further Action letter dated March 9, 2016.